

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 42-Glenville Circle		INSPECTION AREA 1	
LEGAL DESCRIPTION Lot #1062 Glenbrook #10					
TITLE AND NAME Besco		ADDRESS 2777-Alvarado St. San Leandro, Cal.			
GEN. CONTR. Besco		CITY LIC. NO.			
ELEC. CONTR.		ZIP			
PLBG. CONTR.		TEL. NO.			
MECH. CONTR.		ELECTRICAL BY Hammons			
ARCH. ENGR.		DATE 6/20/69			
OWNER Valbrook, Inc.		BUILDING BY Hammons			
CONST. LOAN LENDER		MECHANICAL BY			
BLDG. WIDTH		DATE			
BLDG. LENGTH		PLUMBING BY			
TOTAL HEIGHT		DATE			
NO. OF STORIES		ELECTRICAL BY			
ROOMS		DATE			
AREA 1st FLOOR		TOTAL AREA			
CENSUS TRCT. NO.		C.S.D.			
TOTAL AREA		C.I. CASE			
500-garage 1,394 sq. ft.		ISSUED BY			
SPACES		DATE			
TREES RMVD.		EXISTING BLDG'S SAME LOT			
SIDE YARDS		HOW USED			

NATURE OF WORK:- Const. dwelling & att. garage M.P. #403

PERMIT NO. S.P. - G-2325		ISSUED BY		MICROFILM RECORD	
ISSUANCE DATE 1/9/69		PLANS AND APPLICATION		REEL NO. 252	
VALUATION \$13,800.00		INSPECTION RECORD		FRAME NO. 570	
R.L.F. FEE \$		JOB FILE		REEL NO. 180	
S.M.I. FEE \$				FRAME NO. 276	
PLAN CK. FEE \$				TO 287	
SEWER INCL. FEE \$					
PERMIT FEE \$49.00					
TOTAL FEES \$					

REMARKS AND/OR VARIANCES
DWELLING

8507449-final