

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-2895</i>	LOCATION <i>2033 - Vallis Way</i>
DATE <i>4/19/34</i>	PURPOSE <i>Repairs to Rear Porch</i>
ZONE <i>1</i>	OWNER <i>Charles Zuger</i>
	ARCH'T. <i>Terra Bros</i>
	CONTR. <i>Terra Bros</i>

VAL. <i>13500</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK—REMARKS
	<p data-bbox="268 888 386 925">COMPLETE AND O. K.</p> <p data-bbox="1068 902 1193 925">INSPECTOR</p>