



RECORD OF SUBSEQUENT PERMITS ISSUED

| DATE     | TYPE OF PERMIT AND VALUATION | PERMIT NO. AND FEE    | NATURE OF WORK                             | PRESENT OWNER AND ADDRESS      | CONTRACTOR & ADDRESS                 | FINALED BY | DATE       |
|----------|------------------------------|-----------------------|--|--------------------------------|--------------------------------------|------------|------------|
| 1/2/73   | Mech<br>500.00               | A-7<br>10.50          | install wall heater<br>Dwelling            | F. Kropelin<br>4020 Broadway   | Environmental Cond.<br>1765 35th St. | Reynoso    | 3/20/73    |
| 1/3/73   | Electrical<br>400.00         | A-37<br>10.50         | Rewire<br>Dwelling                         | F. Kropelin<br>4020 Broadway   | Hammons Electric<br>2511 Betsy Way   | Sylliaasen | 3/20/73    |
| 3/21/52  | Building<br>150.00           | B-34700<br>[REDACTED] | Enclose front porch<br>Dwelling            | F. Kropelin<br>4029 Broadway   | owner<br>same                        | Court      | 4/7/52     |
| 7/17/50  | Building<br>250.00           | B-29691<br>[REDACTED] | Repair rear porch<br>Dwelling              | F. Kropelin<br>4020 Broadway   | owner<br>same                        | [REDACTED] | [REDACTED] |
| 5-14-73  | Bldg. \$300.00               | A3750 \$10.50         | Structural repair due<br>to termite damage | Mr. Kroplin<br>5140 8th Avenue | Western Ex. Co.<br>1814 D Street     | Fulles     | 9-26-73    |
| 12-26-72 | Bldg. \$4,000                | H-9873 \$30           | REpair fire damage                         | F. Kroepelin                   | Cal-Sac Const                        | Hammons    | 6-7-73     |

MICROFILM RECORD

| PERMIT NO.      | REEL AND FRAME NOS.   | PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. |
|-----------------|-----------------------|------------|---------------------|------------|---------------------|
| A-7             | R 342 F117            |            |                     |            |                     |
| A-7             |                       |            |                     |            |                     |
| A-37            | R 342 F523            |            |                     |            |                     |
| A-37            |                       |            |                     |            |                     |
| previous Record | R 347 F539            |            |                     |            |                     |
| A-3750          | R 352 F608            |            |                     |            |                     |
| A-3750          | R 344 F552            |            |                     |            |                     |
| H-9873          | R-342 F117            |            |                     |            |                     |
| A-7             | Continued 4161230-231 |            |                     |            |                     |