

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4785</i>	LOCATION <i>1029 - Robertson Way</i>
DATE <i>7/10/40</i>	PURPOSE <i>Erect new dwlg & gar J</i>
ZONE	OWNER <i>David Hill</i>
	ARCH'T.
	CON'T'R. <i>Owner</i>

VAL. <i>4500⁰⁰</i>	STORIES	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
2/12/40	1 ST NSP Frame in place of PW Campbell
3/21/40	2 ND NSP. Frame of PW Campbell
	COMPLETE AND O. K.

INSPECTOR