

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-3475</i>	LOCATION <i>1538 - Santa Ynez</i>			
DATE <i>7/19/39</i>	PURPOSE <i>Erect new dwlg &amp; garage</i>			
ZONE <i>-</i>	OWNER <i>John Friedrich</i>			
	ARCH'T. <i>Owner</i>			
	CONT'R. <i>Owner</i>			
VAL. <i>3800.42</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>	
VENT SHAFTS		BOILER ROOMS	<i>912 #1</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
7/25/39	1 <sup>st</sup> / asp. Form in place <sup>OK</sup> R. H. Campbell
8-10-39	2 <sup>nd</sup> " France " R. H. Campbell
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="340 870 468 906">COMPLETE AND O. K.</span> <span data-bbox="1171 885 1307 906">INSPECTOR</span> </div>