

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-3475</i>		LOCATION <i>1538 - Santa Ynez</i>			
DATE <i>7/19/39</i>		PURPOSE <i>Erect new dwg. & garage</i>			
ZONE <i>-</i>		OWNER <i>John F. Lohr</i>			
		ARCH'T. <i>Owner</i>			
		CONT'R. <i>Owner</i>			
VAL.	<i>3800.42</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS				ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS				BOILER ROOMS	<i>912 #1</i>
OWNER'S INSPECTOR				SPRINKLER SYSTEM	
LATH				GAS VENTS	
FIRE ESCAPES				CHIMNEYS	
STAND PIPES				SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
7/25/39	1 st / asp. Form in place ^{OK} R. H. Campbell
8-10-39	2 nd " France " R. H. Campbell
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>