

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-14000</i>	LOCATION <i>521-8<sup>th</sup> St.</i>
DATE <i>5/7/45</i>	PURPOSE <i>Remodel Basement for living quarters</i>
ZONE	OWNER <i>Don Slaughter</i>
	ARCH'T.
	CONTR. <i>Quone</i>

VAL <i>3500</i>	STORIES	ROOMS	APTS.	SIZE
-----------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK—REMARKS
	<p>1<sup>st</sup> flsp. Cement Floor Slab already in place by Owner on S 1/2 of Basement.</p> <p style="text-align: right;">A. W. Campbell</p>
6/2/25	<p>2<sup>nd</sup> flsp. Frame for 3 Rooms in S 1/2 of Basement.</p>
	<p>Raised Valuation to \$350<sup>00</sup>. Owner did not include some labor in estimated Cost.</p>
	<p>3<sup>rd</sup> flsp. Sheet Rock Walls &amp; Ceiling</p> <p style="text-align: right;">A. W. Campbell</p>
	<p>COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span></p>