

*2351 F 14*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00**

**TYPE BUILDINGS**

<b>PERMIT NO.</b>	<b>S-6125</b>			
<b>DATE</b>	<b>LOCATION</b>	<b>4790-Franklin Blvd. A-3</b>		
<b>3-12-69</b>	<b>PURPOSE</b>	<b>Const. Sign Class N</b>		
<b>ZONE</b>	<b>OWNER</b>	<b>Atlantic Richfield Oil Box 15677</b>		
<b>C-2</b>	<b>ARCH'T</b>			
	<b>CONT'R</b>	<b>Pacific Neon 1576 - Silica Ave.</b>		
<b>VAL.</b>	<b>\$800.</b>	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>
				<b>SIZE</b>
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
				<b>927-0527</b>
<b>FORM</b>				
<b>JOIST</b>				
<b>FRAME SHEET ROCK</b>				
<b>FINAL</b>	<i>10-10-69</i>	<i>M. O'Connor</i>		

11-10-1964

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	<p data-bbox="262 833 383 885"><b>COMPLETE AND OK</b></p> <p data-bbox="1068 859 1189 885"><b>INSPECTOR</b></p>