

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-4307</i>	LOCATION <i>1000 - Q1A</i>
DATE <i>5/14/36</i>	PURPOSE <i>Remodel rear porch & front steps.</i>
ZONE	OWNER <i>Geo. Pappas</i>
	ARCH'T.
	CON'T.R. <i>Pete Lopez</i>

VAL. <i>450⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK - REMARKS
5/15/36	Made Partial Insp of Rebuilding front and rear porches. All porches torn down.
	AW Campbell

COMPLETE
AND O. K.

INSPECTOR