

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <b>A-939</b>	LOCATION <b>4209 T St</b>
DATE <b>Sept 13 1933</b>	PURPOSE <b>Add 1 Bed Rm to rear of Dwlg</b>
ZONE <b>1-Family</b>	OWNER <b>LUELLA AND WALTER LONG</b>
	ARCH'T <b>WALTER LONG</b>
	CONT-R <b>OWNER</b>

VAL. <b>300<sup>00</sup></b>	STORIES <b>1</b>	ROOMS	APTS.	SIZE
---------------------------------	---------------------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
9/18/33	1 <sup>ST</sup> /NSP. Forms for 1 Bed Room Addition. OK A.W. Campbell
10/9/33	2 <sup>ND</sup> /NSP. Frame in place. OK A.W. Campbell
10/11/33	3 <sup>RD</sup> /NSP. Grop Lath Walls & Mastic Ceiling. OK A.W. Campbell
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>