

R284 7303

| | | | | | |
|---------------------------------|-----------------------------|--|-----------------|-------------------------------|------------------------|
| Lot 707 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | \$68.00 |
| Southgate Meadows Unit No. 8 | | TYPE BUILDINGS | | | <i>R2259 7.553-556</i> |
| PERMIT NO. G-7411 | LOCATION 7695 - Millroy Way | | A-5 (49) | | |
| DATE 7-2-70 | PURPOSE | Construct dwelling & garage | | MP 1002 | |
| ZONE R-1 | OWNER | Wilbrook, Inc. 2777 Alvarado, San Leandro | | | |
| | ARCH'T | Leandro | | | |
| | CONTR | Besco, same as owner, 483-4300 | | | |
| VAL. \$17,500. | STORIES | ROOMS | APTS. | 340-gar. SIZE 1,166-sq.ft. | |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | <i>7-3-70</i> | <i>Res</i> | | | |
| JOIST | | | | | |
| FRAME | <i>8-7-70</i> | <i>Coast</i> | | | |
| SHEET ROCK | <i>8-17-70</i> | <i>Coast</i> | | | |
| FINAL | <i>9-23-70</i> | <i>Dana Fuller</i> | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|---|
| 7-13-70 | rk shk Count |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |