

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA	FINAL INSPECTIONS	
		56 Lochmoor Circle					A-5		
LEGAL DESCRIPTION			OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE	
Lot 371 Southgate Meadows #5							Chapin	10/4/66	
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY	DATE
GEN. CONTR. Besco			2777 Alvarado St., San Leandro						
ELEC. CONTR.								PLUMBING BY	DATE
PLBG. CONTR.									
MECH. CONTR.								MECHANICAL BY	DATE
ARCH. ENGR.									
OWNER Barbrook, Inc.			Same					CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER								ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
						1404 (472 gar)			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	CENSUS TRCT. NO.	EXISTING BLDG'S SAME LOT	HOW USED

NATURE OF WORK:- Const. dwlg. & att. gar. Plan 241 B

PERMIT NO. S.P. - F-4533	MICROFILM RECORD			
ISSUED BY	PLANS AND APPLICATION	REEL NO. 128	FRAME NO:- 613	TO 620
ISSUANCE DATE 6/17/66	INSPECTION RECORD	REEL NO. 197	FRAME NO:- 22	TO
VALUATION \$ 13,600.00	JOB FILE	REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$				
S.M.I. FEE \$				
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$ 49.00	REMARKS AND/OR VARIANCES			
\$				
\$				
TOTAL FEES \$				

