

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. 3598	LOCATION 5+6 40 25 24314
	PURPOSE Steel Service Station to Beating
	OWNER J. C. McDonald
	ARCH'T
	CONT'R Land to Be...

PHONES

Passed by 10/18/40

VAL. 4092	STORIES	ROOMS	APTS.	SIZE
------------------	---------	-------	-------	------

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfcd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand-pipes			

DATE

CONDITION OF WORK—REMARKS

**COMPLETED
AND O. K.**

Inspector