

BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 9889	LOCATION 809 Santa Ynez Way			
DATE: Sept. 19, 1938	PURPOSE Re Roof Order with Compensation Expenses			
ZONE Multiple Family	OWNER A. P. DUMONT. 809 Santa Ynez Way			
	ARCH'T			
	CONT-R OWNER			
VAL. 100⁰⁰	STORIES 1	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK--REMARKS
9/23/32	Re Shingling of Roof on Dwy Completed OK A W Campbell
9/23/32	COMPLETE AND O. K. <i>Alfred W Campbell</i> INSPECTOR