

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>2821</i>		LOCATION <i>919 1/2 - 6th</i>			
DATE <i>ISSUED</i>		PURPOSE <i>Remodel w/ upper stories for Hotel 18 Rms.</i>		PHONES	
OWNER <i>J. W. Maguire</i>		ARCHT. <i>J. W. Maguire</i>			
ZONE <i>SACRAMENTO</i>		CONT'R <i>J. W. Maguire</i>			
VAL. <i>15000</i>	STORIES	ROOMS	APTS.	SIZE	
Steel Tested by	<i>OK</i>	Elevator Shafts			
Cement Tested by		Boiler Rooms			
Owner's Inspector Rfd. Conc.		Sprinkler System			
		Floor Tests			
Fire Escapes					
Stand-pipes					



