

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>NO CHARGE PERMIT.</i>	LOCATION <i>411-19th St</i>		
DATE <i>APR. 21 1931</i>	PURPOSE <i>Make repairs to front steps. (Dry Rot)</i>	ROOMS	APTS.
ZONE <i>Multiple Family</i>	OWNER <i>MARIE SMUCK</i>	PHONE	
	ARCH'T		
	CONT'R <i>JOS COREY</i>		
	VAL. <i>25⁰⁰</i>	STORIES <i>1</i>	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Jolts						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE

CONDITION OF WORK—REMARKS

9/3/27

Resurfacing of Roof of Dock Completed
All Complete

COMPLETED
AND O. K.

INSPECTOR