

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-499</i>	LOCATION <i>1616 - 3<sup>rd</sup> Ave</i>
DATE <i>3/1/45</i>	PURPOSE <i>New dwg.</i>
ZONE	OWNER <i>O.A. Tucker</i>
	ARCH'T.
	CONT'R. <i>Myron L. Moore</i>

VAL. <i>6000<sup>00</sup></i>	STORIES <i>10</i>	ROOMS <i>7</i>	APTS.	SIZE
----------------------------------	----------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area</i> <i>1650<sup>00</sup>'</i> <i>@ 324</i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
3/12/43	1 <sup>ST</sup> /NSP. Frame in place <sup>OK</sup> <i>AW Campbell</i>
' 20	2 <sup>ND</sup> /NSP. Frame <sup>OK</sup> <i>AW Campbell</i>
5 <sup>4</sup> /3/43	3 <sup>RD</sup> /NSP. INT. LATH <sup>OK</sup> <i>AW Campbell</i>
	<p data-bbox="310 1034 462 1080">COMPLETE AND O. K.</p> <p data-bbox="1307 1053 1466 1076">INSPECTOR</p>