

*P-60*

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD *F380-381*

**TYPE BUILDINGS \$6.00**

|                             |   |            |
|-----------------------------|---|------------|
| PERMIT NO.<br><i>D-3214</i> | LOCATION <i>1070 Piedmont Drive</i>                         | <i>A-3</i> |
| DATE<br><i>Sent. 8.50</i>   | PURPOSE <i>Const patio roof rear dwelling</i>               |            |
| ZONE<br><i>R-1</i>          | OWNER   |            |
|                             | ARCH'T  |            |
|                             | CONT'R <i>Taylor &amp; Larsen 4008- 12th Avenue GL 1-33</i> |            |

|                    |         |       |       |                           |
|--------------------|---------|-------|-------|---------------------------|
| VAL. <i>\$825.</i> | STORIES | ROOMS | APTS. | SIZE<br><i>552 Sq.ft.</i> |
|--------------------|---------|-------|-------|---------------------------|

*54*

| INSP. | DATE           | INSPECTOR    |
|-------|----------------|--------------|
| FORM  |                |              |
| JOIST |                |              |
| FRAME |                |              |
| LATH  |                |              |
| FINAL | <i>3-21-60</i> | <i>Court</i> |



| DATE | SPECIAL CONDITIONS OF WORK—REMARKS   |
|------|--|
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      | <b>COMPLETE AND OK</b> <span style="float: right;"><b>INSPECTOR</b></span> |