

FINAL INSPECTIONS		CITY OF SACRAMENTO BUILDING INSPECTIONS DIVISION			JOB ADDRESS 40 Caselli Circle			AREA 5R
BUILDING BY	DATE	ASSESSOR PARCEL NUMBER	LEGAL DESCRIPTION					
ELECTRICAL BY	DATE	NAME OF FIRM	ADDRESS	ZIP CODE	ACCT. NO.	PHONE NO.		
PLUMBING BY	DATE	CONTRACTOR						
MECHANICAL BY	DATE	OWNER						
CERTIFICATE OF OCCUPANCY ISSUED BY	DATE	ARCH. ENGR.						
MICROFILM RECORD		CONST. LOAN LENDER						

PLANS AND APPLICATION			NO. OF STORIES	ROOF COVERING	AREA 1ST FLOOR	TOTAL AREA	GARAGE AREA	PATIO AREA	USE ZONE	BUILDING ELECT. MECH. PLUMB.	
REEL NO.	FRAME NO:-	TO	THIS PERMIT IS FOR: <input type="checkbox"/> BUILDING <input type="checkbox"/> MECHANICAL <input type="checkbox"/> PLUMBING <input type="checkbox"/> ELECTRICAL	NATURE OF WORK IN DETAIL							PERMIT-#
REEL NO.	FRAME NO:-	TO									
REEL NO.	FRAME NO:-	TO									
REEL NO.	FRAME NO:-	TO									
REEL NO.	FRAME NO:-	TO									
REEL NO.	FRAME NO:-	TO									

REMARKS AND/OR VARIANCES	VALUATION \$	OCCUP. GROUP
	ISSUED BY:	
	DATE ISSUED	
	BUILDING PERMIT FEE \$	
	PLAN CHECK FEE \$	
	RDF FEE \$	
	S.M.I. FEE \$	
	REG. SEWER FEE \$	
	BRIDGE FEE \$	
	CONST. TAX \$	
TOTAL FEES \$		

OFFICE COPY
REV. 9/79

AREA
JOB ADDRESS
40 Caselli Circle

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
1-22-82	E \$50.	1-10345R \$7.50	Repair main panel	Stocton Buck Box 36015 S.F.	You Name It Repair 7538 Saybrook Dr.	<i>[Signature]</i>	1/25/82

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
1-10345R	R 10061227				
	R 7068327				
	R 7088493				

[Handwritten notes and signatures]
 1-10345R
 R 10061227
 R 7068327
 R 7088493