

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>15-4257</i>	LOCATION <i>1414 - 31<sup>st</sup> Street</i>			
DATE <i>7/26/40</i>	PURPOSE <i>Lower dwls repair &amp; extend</i>			
ZONE	OWNER <i>Mable Waterley</i>			
	ARCH'T.			
	CON'T.R. <i>Rae Baltz</i>			
VAL <i>2000<sup>00</sup></i>	STORIES <i>6</i>	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
3/2/21	<p> <i>Work completed on Rd 2 St. Driv.</i>  <i>Covered down about 2 hours.</i>  <i>For set in with new 2 - for</i>  <i>over pipe for. (K. H. H. H. H.)</i>  <i>J. K. H. H. H.</i> </p>
	<p> <b>COMPLETE AND O. K.</b> <span style="float: right;"><b>INSPECTOR</b></span> </p>