

*B112 7564*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$13.00**

**TYPE BUILDINGS**

PERMIT NO. <b>E-2886</b>	LOCATION <b>2345 - Portola Way</b>	<b>A-2</b>
DATE <b>Dec. 17-62</b>	PURPOSE <b>Repair fire damage to dwelling.</b>	
ZONE <b>R-1</b>	OWNER <b>Mrs. Keller</b>	<b>Same</b>
	ARCH'T <b>GL 2-3131</b>	
	CONTR <b>Peterson &amp; Assoc. 1810 - 28th Street</b>	

VAL <b>\$2,000.</b>	STORIES	ROOMS	APTS.	SIZE
---------------------	---------	-------	-------	------

INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP
FORM			
JOIST			
FRAME	<i>12/28/62</i>	<i>Court.</i>	
SHEET ROCK			
FINAL	<i>2-12-63</i>	<i>[Signature]</i>	

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
12-31-62	PT 40 job card 4 PMS
	COMPLETE AND OK <span style="float: right;">INSPECTOR</span>