

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. 5173	LOCATION 1131-11 2nd St
DATE 9/27/29	PURPOSE Sign
ZONE 1	OWNER Hydrolite Co
	ARCH'T Reliable Elevator
	CONTR Reliable Elevator
	PHONES

VAL. 250-	STORIES	ROOMS	APTS.	SIZE
---------------------	---------	-------	-------	------

Steel Tested by		Elevator Shafts	
Cement Tested by		Boller Rooms	
Owner's Inspector Rfd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand-pipes			

DATE

CONDITION OF WORK—REMARKS

**COMPLETED
AND O. K.**

INSPECTOR