

R231 E-597-602

Lot 586

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$67.00

Greenhaven #4

TYPE BUILDINGS

| | | | | |
|----------------------|-----------------------------|------------------------------|--------------------|------------------------------|
| PERMIT NO. F-9371 | LOCATION 86 Parklite Circle | | A-3 | |
| DATE 1-19-68 | PURPOSE | Const. dwelling with garage | | |
| ZONE R-1 | OWNER | Basford 6660 Havenside Drive | | |
| | ARCH'T | | | |
| | CONTR | Owner same 428-7853 | | |
| VAL \$20,000. | STORIES | ROOMS | APTS. | 443 gar. SIZE 2103 sq.ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | 1-26-68 | E. Larson | | |
| JOIST | 3-13-68 | Const | | |
| FRAME | 3-14-68 | E. Larson | | |
| SHEET ROCK | 3-18-68 | Const | | |
| FINAL | 5-3-68 | E. Larson | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|---|
| 8-9-65 | PT Cabinet - Grade at-wood at |
| | joists. F.P. hds. strap. 3" clearance |
| | under ducts. Purlins must clear concrete |
| | by 1/2" Laser |
| 8-13-65 | PT GYM - Ground not complete |
| | Est. Blue Laser |
| | |
| | |
| | <div style="display: flex; justify-content: space-between;"> COMPLETE AND OK INSPECTOR </div> |