

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-4573</i>	LOCATION <i>1081 — Robertson Way</i>
DATE <i>1/6/46</i>	PURPOSE <i>Erect new dwelling</i>
ZONE	OWNER <i>Dave Hill</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>4500.00</i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>1311<sup>sq</sup></i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 3.5</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
1/12/20	1 <sup>ST</sup> / NSP. T-Forms in place <sup>OK</sup> <i>Red Campbell</i>

COMPLETE  
AND O. K.

INSPECTOR