

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4573</i>	LOCATION <i>1081 — Robertson Way</i>
DATE <i>1/6/46</i>	PURPOSE <i>Erect new dwelling</i>
ZONE	OWNER <i>Dave Hill</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>4500.00</i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>1311^{sq}</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 3.5</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
11/12/20	1 ST / NSP. T-Forms in place ^{OK} <i>Red Campbell</i>
	<p data-bbox="299 854 435 896">COMPLETE AND O. K.</p> <p data-bbox="1120 870 1263 896">INSPECTOR</p>