

*R-323 1263*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**\$Gratis**

*Expires - 3.17.69*  
*initial 2-22-69* **TYPE BUILDINGS** *(29) 1335-337 file*

**PERMIT NO.**  
**W-4341**

**DATE**  
**Jan-21-69**

**ZONE**

**LOCATION** 617 - South Avenue A-7 (67)

**PURPOSE** Wreck 1-family dwelling

**OWNER** Mr. McKinley Williams 3825 - Lilly

**ARCH'T** 925-4475

**CONTR** Owner Same

<b>VAL.</b>	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
-------------	----------------	--------------	--------------	-------------

<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
--------------	-------------	-------------------	------------------------	----------------------

**FORM**

**JOIST**

**FRAME**

**SHEAT**

**V.C.**

**FINAL** *4.23.70* *Chapin* *Grd*

*Condensed by Gen. Department*  
*2-25-69.50.*

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
3-5-69	Extended to 3-17-69 <i>Center</i>
4-22-69	Referred to Attorney's office - <i>Chapin</i>
6-25-69	<i>Shows, not clear. Names said to would come in for several hours</i>
7-3-69	<del>Ref</del> Referred to Hawaii - <i>Chapin</i>
10-10-69	Tracks debris on lot looks like a dumping yard - no portion of of dwelling left <i>Hawaiians</i>
11-21-69	Referred to attorney <i>Chapin</i>
	COMPLETE AND OK
	INSPECTOR