

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-15165</i>	LOCATION <i>231 - Jay McInnis Way</i>			
DATE <i>7/1/46</i>	PURPOSE <i>Erect new double garage</i>			
ZONE	OWNER <i>Charles E. Kemp</i>			
	ARCH'T.			
	CONT'R. <i>Markward C.</i>			
VAL. <i>5000<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>794<sup>00</sup></i>	
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
2/21/46	1 <sup>st</sup> Insp. Forms for New Dirly & George R. W. [unclear]
6/12/46	Frame Insp. D. E. Buckins.
COMPLETE AND O. K.	INSPECTOR