

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS				INSPECTION AREA		FINAL INSPECTIONS		
		2912 Belmar St.				1				
LEGAL DESCRIPTION				OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE			
Glenbrook #2 Lot 177										
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	BUILDING BY	DATE	
Besco			2777 Alvarado St.					<i>Hansen</i>	<i>11/23/65</i>	
GEN. CONTR.								ELECTRICAL BY	DATE	
ELEC. CONTR.										
PLBG. CONTR.								PLUMBING BY	DATE	
MECH. CONTR.										
ARCH. ENGR.								MECHANICAL BY	DATE	
OWNER								CERTIFICATE OF OCCUPANCY		
Brookvale, Inc.										
CONST. LOAN LENDER								ISSUED BY		DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
			1			1,327				
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		

NATURE OF WORK:- Const. dwelling & att. garage Plan 402

PERMIT NO. S.P. -	F-2242	MICROFILM RECORD			
ISSUED BY					
ISSUANCE DATE	11-8-65	PLANS AND APPLICATION	REEL NO. 180	FRAME NO:- 491	TO 501
VALUATION	\$13,100.00	INSPECTION RECORD	REEL NO. 195	FRAME NO:- 314	TO 318 (rev.)
R.D.F. FEE	\$	JOB FILE	Combine	REEL NO. F 288	FRAME NO. 289
S.M.I. FEE	\$				
PLAN CK. FEE	\$				
SEWER INCL. FEE	\$				
PERMIT FEE	\$ 49.00	REMARKS AND/OR VARIANCES			
	\$	Dwelling			
	\$				
TOTAL FEES	\$				

