

R 242 F 423 - 430

ptn. of Lot 7, 8, & 9. **BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$146.00
TYPE BUILDINGS *R251 F111 walls*
R251 F123 - file

PERMIT NO. G-972 **LOCATION** 1501 - Silica Avenue A-6 (55.02)
DATE July-19-68 **PURPOSE** Const. bldg. for glass service area.
OWNER A. Ratzlaff Same
ZONE M92 **ARCH'T** Leo Mc Glade 2011 - Arden Way
CONTR L.J. Fetch Const. 170 - Southgate Rd.

VAL. \$51,000. **STORIES** **ROOMS** **APTS.** 1,680 sq. ft. **SIZE** 9,800 sq. ft.
INSP. **DATE** **BLDG. TYPE** III No Hr. **OCCUPANCY GROUP** F-2 **PHONE (O) (C)** 922-3657

FORM
JOIST
FRAME *9-20-68 Luller*
SHEET ROCK *9-25-68 Luller*
FINAL *11-2-68 C. Harmon* *Cont*



DATE	SPECIAL CONDITIONS OF WORK — REMARKS	
7-25-68	OK Steel not in place	Hammons
7-26-68	OK wires	Hammons
7-31-68	OK 4 base slab	Chapin
8-2-68	OK floor slab	Hammons
8-7-68	Jct. up - Unable to make	Chapin
8-8-68	OK 8 Panels - Chapin	Chapin
8-9-68	OK 6 Panels	J. DeW
8-12-68	OK Panels 32-12-13-17	Hammons
8-13-68	OK Panels 18	Hammons
8-14-68	OK 2 Panels	Chapin
8-26-68	OK 12 Columns	Hammons
8-27-68	OK 6 end columns	Hammons
8-30-68	OK Columns steel	Hammons
8-11-68	OK roof joist - J. DeW	J. DeW
11-6-68	OK - Plans not followed	Kidd
11-12-68	COMPLETE AND OK	Hammons

INSPECTOR