

3817 Mahogany Street.

3817 - Mahogany St.

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
10/19/77	B. \$ 2000.00	E-8329 \$ 50.00	Termite Repair and dry rot-Dwlg	William Ambus Same	Hydrex 1213 Arden Way 95815	NO FINAL INSPECTION CALLED BY PERMITEE	
11/1/77	B. \$ 300.00	E-8751 \$ 20.00	Reroof Garage -Dwlg	R. Tatro 907 Linvale Ct.	Donald Jennings 8100 La Rivera Dr. 95826	NO FINAL INSPECTION CALLED BY PERMITEE.	3-26-80
11/7/77	M. \$ 500.00	E-8983 \$ 20.00	Heating & A/C system to code-Dwlg	Grayson Same	Norms Sheet Metal P.O. Box 22358 95822	Cabral	11-18-77
11/7/77	B&E \$500.00	E-9022 \$20.00 6-4852	Code Req Correction	William Ambus Same	Hydrex Pest 1213 Arden Way 95815	Cabral Cabral	11-18-77 11-18-77
2-3-81	B,M,P,E,\$12000.00	H10467,\$185.00	Fire Damage	Lloyd Allen 3817 Mahogany	Owner 3817 Mahogany	B. J. J. J. B. J. J. J. B. J. J. J.	3/23/81 3/23/81 3/23/81
8-18-82	E. \$50.00	J-3195R \$7.50	E. Reconnect & Minor Repair. H-13095	James W. Jones 641 Elkhorn Blvd	Owner'	WILLIAMS	8-18-82

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
E-8329	R499F128	H-10467	R733F108		
E-8751	R500F016	E-9022	R733F109		
E-8983	R500F326	J-3195R	R742F087		
E-9022	R500F326-327		R743F104		
E-8983	0617F167				
E-9022	0617F167				
E-8751	0617F167				
H10467	R659F157				

PM
E
B

