

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
5999 Holstein Way		3		FINAL INSPECTIONS	
LEGAL DESCRIPTION					
Lot 291 S. 1d. Pk. Hill #4					
TITLE AND NAME					
Owner					
GEN. CONTR.					
ELEC. CONTR.					
PLBG. CONTR.					
MECH. CONTR.					
ARCH. ENGR.					
OWNER					
Harlow Const.					
CONST. LOAN LENDER					
BLDG. WIDTH					
BLDG. LENGTH					
TOTAL HEIGHT					
NO. OF STORIES					
ROOF CONSTR.					
AREA 1st FLOOR					
TOTAL AREA					
C.S.D.					
C.I. CASE					
CENSUS TRCT. NO.					
2,300 sq. ft.					
EXISTING BLDG'S SAME LOT					
TREES RMVD.					
SPACES					
PARK'G REQ.					
SIDE YARDS					
REAR YARDS					
SET BACK REQ.					
USE ZONE					
PARK'G REQ.					
SPACES					
TREES RMVD.					
EXISTING BLDG'S SAME LOT					
HOW USED					

NATURE OF WORK:- Const. dwelling & garage

PERMIT NO. S.P. D-2095		ISSUED BY	
5/27/59		ISSUANCE DATE	
\$ 21,000.00		VALUATION	
\$		R.U.F. FEE	
\$		S.M.I. FEE	
\$		PLAN CK. FEE	
\$		SEWER INCL. FEE	
\$ 50.00		PERMIT FEE	
\$		TOTAL FEES	
PLANS AND APPLICATION			
REEL NO. 56	FRAME NO. 386	TO	393
INSPECTION RECORD	REEL NO.	FRAME NO.	TO
JOB FILE	REEL NO.	FRAME NO.	TO
MICROFILM RECORD			
REMARKS AND/OR VARIANCES			
DWELLING			

R514B561 - Harlow