

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>2nd City</i>	LOCATION <i>East 14th Street Council 10/13/31 1741 Street Council</i>		
DATE <i>10/13/31</i>	PURPOSE <i>Install 4 - 500 - 1 - 1000 Gal Gas Tank & Pump</i>	PHONES	
ZONE <i>Gen Com</i>	OWNER <i>Center Mill Lumber Co</i>	ARCH'T <input checked="" type="checkbox"/>	
	CONT'R <i>Kaiser Bros (LESEE)</i>		

VAL. <i>2000</i>	STORIES	ROOMS	APTS.	SIZE
----------------------------	----------------	--------------	--------------	-------------

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfcd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand Pipes			

DATE	CONDITION OF WORK—REMARKS
	COMPLETED AND O.K. INSPECTOR.

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>Tracy</i>	LOCATION <i>1741 - Stockton Blvd</i>			
DATE <i>5/5/32</i>	PURPOSE <i>Machine 2 - Walls on Serv. In Bldg</i>	PHONES		
ZONE <i>Low Plat</i>	OWNER <i>Texas Oil Co.</i>	ARCH'T		
	CONT-R <i>Owner</i>			
VAL. <i>30 -</i>	STORIES	ROOMS	APTS.	SIZE
Light Shafts			Elevator Shafts	
Vent Shafts			Boiler Rooms	
Owner's Inspector			Sprinkler System	
Lath			Gas Vents	
Fire Escapes			Chimneys	
Stand Pipes			Skylights	

DATE	CONDITION OF WORK--REMARKS
5/5/32	Frame Drip for 2 walls enclosing Compressor 2 Gas Pumps removed - OK Alder Campbell
5/9/32	COMPLETE AND O. K. Alder Campbell INSPECTOR