

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 106 Glenville Circle					INSPECTION AREA 1	FINAL INSPECTIONS		
LEGAL DESCRIPTION Lot 1096 Glenbrook #10					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY Calloway	DATE 7/3/70
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO. 383-9315		ELECTRICAL BY	DATE
GEN. CONTR.	Besco		Same						PLUMBING BY	DATE
ELEC. CONTR.									MECHANICAL BY	DATE
PLBG. CONTR.										
MECH. CONTR.										
ARCH. ENGR.										
OWNER	Valbrook, Inc.		2777-Alvarado St. San Leandro						CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER								ISSUED BY		DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOMS	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
			1	5	462-garage	1,525 sq. ft.				
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		

NATURE OF WORK:- **Const. dwelling & garage Plan 101**

PERMIT NO. S.P. - G-5266	MICROFILM RECORD				
ISSUED BY	PLANS AND APPLICATION	REEL NO. 272	FRAME NO:- 277	TO	
ISSUANCE DATE 12/4/69	INSPECTION RECORD	REEL NO. 229	FRAME NO:- 71	TO	80-plans
VALUATION \$ 23,000.00	JOB FILE	REEL NO.	FRAME NO:-	TO	
R.D.F. FEE \$					
S.M.I. FEE \$					
PLAN CK. FEE \$					
SEWER INCL. FEE \$					
PERMIT FEE \$ 83.00	REMARKS AND/OR VARIANCES				
	Dwelling				
TOTAL FEES \$					

RS 07221 - final

