

Q 173 7127-133

Lot 198		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$64.00
S.L.P. Hills #28		TYPE BUILDINGS			
PERMIT NO.					
F-1121	LOCATION	28 & 40 Rosemead Circle		A-5	
DATE	PURPOSE	Const. duplex and attached garages			
July 12-65	OWNER	Lee Basford 6660-Havenside Drive			
ZONE	ARCH'T				
R-1	CONTR	Owner same 422-0972			
VAL. \$19,000.		STORIES	ROOMS	APTS.	761-gar. SIZE 1897 sq. ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	7-14-65	Build			
JOIST	7-23-65	Fuller			
FRAME	8-25-65	Fuller			
SHEET ROCK	8-31-65	Basford			
FINAL	10/10/66	Dana E. Fuller			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
7-31-65	Pt Grout - fill sewer ditch. Remove large dirt clump. Maintain 1" clearance between dirt & wood at pier's Chapin
8-24-65	Pt frame - Set around furnace ^{filler} same ceiling
8-30-65	Pt SR - 70 plane on case. Ribs
10-8-65	P.I. Pinal - until shaver taken care of (inside) OK to occupy, but no Pinal (Pinal)
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND OK INSPECTOR </div>