

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS				INSPECTION AREA	FINAL INSPECTIONS	
		135-Glenville Circle				1		
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE
Lot 1107 Glenbrook #11								
TITLE AND NAME		I/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	BUILDING BY
GEN. CONTR. Besco			2777-Alvarado Street					Calloway
ELEC. CONTR.								12/14/70
PLBG. CONTR.								ELECTRICAL BY
MECH. CONTR.								DATE
ARCH. ENGR.								PLUMBING BY
OWNER Mattbrook, Inc.			2777-Alvarado St. San Leandro					MECHANICAL BY
CONST. LOAN LENDER								DATE
BLDG. WIDTH		BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.
						447-garage	1,327 sq. ft.	CENSUS TRCT. NO.
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED

NATURE OF WORK:- Construct dwelling & garage MP#402

PERMIT NO. S.P. - 0-8646		MICROFILM RECORD					
ISSUED BY							
ISSUANCE DATE 10/5/70		PLANS AND APPLICATION	REEL NO. 289	FRAME NO:- 210	TO		
VALUATION \$ 20,100.00		INSPECTION RECORD	REEL NO. 180	FRAME NO:- 491	TO 501		
R.D.F. FEE \$		JOB FILE	REEL NO. 197	FRAME NO:- 553	elevation		
S.M.I. FEE \$			195	314	318 joist		
PLAN CK. FEE \$							
SEWER INCL. FEE \$							
PERMIT FEE \$ 77.00		REMARKS AND/OR VARIANCES					
		DWELLING					
TOTAL FEES \$							

*05078646 - final*

