

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 4601 Brookfield Drive					INSPECTION AREA A-5	FINAL INSPECTIONS		
LEGAL DESCRIPTION Lt. 79 Southgate Meadows #1					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY Larsen	DATE 4-1-64
TITLE AND NAME		V/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		ELECTRICAL BY	DATE
GEN. CONTR. Besco									PLUMBING BY	DATE
ELEC. CONTR.									MECHANICAL BY	DATE
PLBG. CONTR.										
MECH. CONTR.										
ARCH. ENGR.										
OWNER Valbrook, Inc									CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER									ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	472 Gar AREA	C.S.D.	C.I. CASE		
			1			1404 sq ft	CENSUS TRCT. NO.			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		
			R-1							
NATURE OF WORK:- Const. dwelling and garage Plan 241										
PERMIT NO. S.P. E-5420		MICROFILM RECORD								
ISSUED BY										
ISSUANCE DATE	10-22-63	PLANS AND APPLICATION	REEL NO. 131	FRAME NO:- 249	TO	R128 F613-620				
VALUATION	\$ 13,600	INSPECTION RECORD	REEL NO. 416	FRAME NO:- 378	TO					
R.D.F. FEE	\$	JOB FILE	REEL NO.	FRAME NO:-	TO					
S.M.I. FEE	\$									
PLAN CK. FEE	\$									
SEWER INCL. FEE	\$									
PERMIT FEE	\$	REMARKS AND/OR VARIANCES								
	\$	Form: 12-17-63 Hammons								
	\$	Joist: 1-9-64 Larsen								
TOTAL FEES	\$ 49	Frame: 2-10-64 Court								
		Sheet Rock: 2-17-64 Riolo								

