

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-34076</i>	LOCATION <i>144 - San Antonio Way.</i>
DATE <i>Jan 5-51</i>	PURPOSE <i>Erect new dwg. & garage</i>
ZONE	OWNER <i>G. Tibiotta J</i>
	ARCH'T.
	CON'T'R. <i>John Jacobson Const.</i>

VAL. <i>6000⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	PSIZE <i>1220</i>
-------------------------------	---------------------	-------------------	-------	----------------------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
12/11/51	Frame Insp. P. E. Puckius
1/11/52	Frame Insp. (Flue to be corrected) P. E. P.
3-19-52	Final R. E. Conti
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>