

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA	FINAL INSPECTIONS	
		3083 Bridgeford Drive					A-6		
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	
Larchmont Northgate #2 Lot 142									
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		
GEN. CONTR. Owner									BUILDING BY Riolo
ELEC. CONTR.									DATE 12-14-70
PLBG. CONTR.									ELECTRICAL BY
MECH. CONTR.									DATE
ARCH. ENGR.									PLUMBING BY
OWNER Larchmont Northgate									DATE
CONST. LOAN LENDER									MECHANICAL BY
									DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	CERTIFICATE OF OCCUPANCY
						467 GAR 1150 sq ft			ISSUED BY
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	CENSUS TRCT. NO.	EXISTING BLDG'S SAME LOT	DATE
			R-1						

NATURE OF WORK:- Const. dwelling and garage MP #234

PERMIT NO. S.P. - G-7620		MICROFILM RECORD				
ISSUED BY		PLANS AND APPLICATION		REEL NO. 285	FRAME NO:- 386	TO °
ISSUANCE DATE Jul 22-70		INSPECTION RECORD		REEL NO. 410 F 598	FRAME NO:- 397	Compound
VALUATION \$ 17,800		JOB FILE		REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$						
S.M.I. FEE \$						
PLAN CK. FEE \$						
SEWER INCL. FEE \$						
PERMIT FEE \$						
TOTAL FEES \$ 68		REMARKS AND/OR VARIANCES				
		Form: 8-17-70 Riolo				
		Frame: 9-24-70 Hammons				
		Sheet Rock: 10-1-70 Hammons				