

| | | | | | |
|----------------------|--------------------------------------|--|-----------|--------------|---------|
| Lot #278 | | BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD | | | \$47.00 |
| So. Id. Pk. Hills 23 | | TYPE BUILDINGS | | | |
| PERMIT NO. | LOCATION 1359 - San Clemente Way A-3 | | | | |
| D-9051 | PURPOSE Const. dwlg. & att. gar. | | | | |
| DATE | OWNER Ruben Weber 1733 - Crestwood | | | | |
| 7-12-61 | ARCH'T | | | | |
| ZONE | CONT'R | | | | |
| R-1 | Owner | Same | GA 8-2157 | | |
| VAL \$18,700 | STORIES | ROOMS | APTS. | 462 gar. | SIZE |
| | 1 | | | 1909 sq. ft. | |
| INSP. | DATE | INSPECTOR | | | |
| FORM | 7-13-61 | <i>Barbato</i> | | | |
| JOIST | 7-26-61 | <i>Jones</i> | | | |
| FRAME | 8-28-61 | <i>Barbato</i> | | | |
| LATH | 9-30-61 | <i>Jones</i> | | | |
| FINAL | 10-21-61 | <i>Barbato</i> | | | |

| DATE | SPECIAL CONDITIONS OF WORK—REMARKS |
|--------|---|
| 7-1-36 | Checked pins blocks & top rails used. Instructed to use 2nd. (k again) on post top ^{boards} |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK INSPECTOR |