

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-7186</i>	LOCATION <i>2173 - P 20</i>
DATE <i>10/8/37</i>	PURPOSE <i>Repairs to roof re-shingle</i>
ZONE	OWNER <i>Mrs. G. Hunter</i>
	ARCH'T.
	CON'T.R. <i>Wm. J. Lee</i>

VAL. <i>17500</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	COMPLETE AND O. K.
	INSPECTOR