

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
7/28/76	B. \$ 600	D-5824 \$ 15	Reroof	George Desousa Same	Owner Same	<i>Riolo</i>	<i>8/4/76</i>
5/20/79	B.M.P. E. \$ 20,000.00	G-2366 \$ 257.00	Add bedroom bath and kitchen Plus heat and A/C for dlwg	De souza Same	Tim Holland Custom Bldg 2417 18th St 95818	<i>NO FINAL INSPECTION</i>	
1-18-82	P \$220.	I-10223R \$20.	Gas test due to leak.	M. Desousa 2900 Carolyn Way	Owner 2900 Carolyn Way	<i>Lacey</i>	<i>1/20/82</i>

NO FINAL INSPECTION CALLED BY PERMITTEE

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
B-22125					
D-5824	R451F285				
D-5824	R452F188				
G-2366	R562F629				
G-2366	R563F020-023 plano				
I-10223R	R705F319				
I-10223R	R706F79				

final

final

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
2900 Carolyn Way				3	
LEGAL DESCRIPTION					
2900 Carolyn Way					
TITLE AND NAME					
OWNER					
OWNER Alan Olson					
CONST. LOAN LENDER					
BLDG. WIDTH					
BLDG. LENGTH					
TOTAL HEIGHT					
NO. OF STORIES					
ROOF CONSTR.					
AREA 1st FLOOR					
TOTAL AREA					
C.S.D.					
C.I. CASE					
CENSUS TRCT. NO.					
EXISTING BLDG'S SAME LOT					
HOW USED					
SIDE YARDS					
REAR YARDS					
SET BACK REQ.					
USE ZONE					
PARK'G REQ.					
SPACES					
TREES RMVD.					
NATURE OF WORK:- Direct new DWLG					

PERMIT NO. S.P. - B-22123		ISSUED BY	
5/7/48		5375	
VALUATION		\$	
PLANS AND APPLICATION		REEL NO. 511285	
INSPECTION RECORD		REEL NO. 511285	
JOB FILE		REEL NO. TO	
R.D.F. FEE		FRAME NO. TO	
S.M.I. FEE		FRAME NO. TO	
PLAN CK. FEE			
SEWER INCL. FEE			
PERMIT FEE			
TOTAL FEES			
REMARKS AND/OR VARIANCES			
MICROFILM RECORD			