

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B 8098</i>	LOCATION <i>864 - Robertson Way</i>
DATE <i>4/26/41</i>	PURPOSE <i>New garage for</i>
ZONE <i>—</i>	OWNER <i>H. H. Lund</i>
	ARCH'T.
	CONTR. <i>O'Connor</i>

VAL. <i>5000</i>	<i>65</i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
------------------	-----------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS		BOILER ROOMS	<i>133901</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 350</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
4/30/41	1 ST /NSP. Forms in place ^{OK} A.W. Campbell
5/26/41	2 ND /NSP. Frame " " " " ^{OK} A.W. Campbell
6/10/41	3 RD /NSP. INT + EXT LAZY ^{OK} A.W. Campbell
7/15/41	4 TH /NSP. Duly + Garage Completed ^{OK}
7/15/41	<div style="display: flex; justify-content: space-between; align-items: center;"> COMPLETE AND O. K. Alden W. Campbell INSPECTOR </div>