

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS				INSPECTION AREA		FINAL INSPECTIONS	
		99-Glenville Circle				1			
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	
Lot 1043 Glenbrook #10									
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	BUILDING BY	DATE
GEN. CONTR. Besco			Same				383-9315	Hammons	5/23/69
ELEC. CONTR.								ELECTRICAL BY	DATE
PLBG. CONTR.								PLUMBING BY	DATE
MECH. CONTR.								MECHANICAL BY	DATE
ARCH. ENGR.									
OWNER Barbrook, Inc.			2777-Alvarado St. San Leandro, Cal.					CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER								ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
			1		500-garage	1,394 sq. ft.			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED	

NATURE OF WORK:- Const. dwelling & garage Plan #403

PERMIT NO. S.P. - G-2317	MICROFILM RECORD			
ISSUED BY	PLANS AND APPLICATION	REEL NO. 252	FRAME NO:- 561	TO
ISSUANCE DATE 1/9/69	INSPECTION RECORD	REEL NO. 180	FRAME NO:- 276	TO 287
VALUATION \$ 13,800.00	JOB FILE	REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$				
S.M.I. FEE \$				
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$ 49.00	REMARKS AND/OR VARIANCES			
\$	DWELLING R 1098F366			
\$				
TOTAL FEES \$				

8507F648 - Special

