

2166 7351

## BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$5.00

## TYPE BUILDINGS

PERMIT NO. F-278		LOCATION 1913 - 3rd Street		A-2	
DATE Apr 20-65		PURPOSE Reaplace rear porch, chimney & gen. repair		OWNER Pedro Lopez same	
ZONE R-1		ARCH'T		CONTR Owner	
VAL \$500.		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	4-28-65	Wabito			
JOIST					
FRAME					
SHEET ROCK					
FINAL	6-25-65	E. Larsen			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
5-25-65	Pt Frame - must have more bracing
	a blocking on porch
	Person

COMPLETE  
AND OK

INSPECTOR