

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10816</i>	LOCATION <i>3400 - Sophia Way.</i>
DATE <i>10/23/42</i>	PURPOSE <i>Erect new double garage</i>
ZONE	OWNER <i>Willard Houser</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>4000</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
------------------	---------------------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area 928^{sq} @ 350</i>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
11/4/42	1 st Jump Form OK with
11/27/42	2 " Form OK with
12/9/42	3 rd / NSP. INT & EXT LATH ^{OK} A.W. Campbell
2/15/43	4 th / NSP. Dwg with Attached Grage Completed OK

2/15/43	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. Allen W. Campbell INSPECTOR </div>