

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
4590 Cedarwood Way		5		FINAL INSPECTIONS	
LEGAL DESCRIPTION					
lot 115 Southgate Meadows #2					
TITLE AND NAME					
Besco					
GEN. CONTR.					
ELEC. CONTR.					
PLBG. CONTR.					
MECH. CONTR.					
ARCH. ENGR.					
OWNER					
Valbrook Inc.					
4725 Thornton Ave.					
CERTIFICATE OF OCCUPANCY					
CONST. LOAN LENDER					
BLDG. WIDTH					
BLDG. LENGTH					
TOTAL HEIGHT					
NO. OF STORIES					
ROOF CONSTR.					
AREA 1st FLOOR					
TOTAL AREA					
C.S.D.					
C.I. CASE					
SIDE YARDS					
REAR YARDS					
SET BACK REQ.					
USE ZONE					
1					
PARK'G REQ.					
SPACES					
TREES RMVD.					
EXISTING BLDG'S SAME LOT					
HOW USED					

NATURE OF WORK:-

Const dwelling and att garage;

PERMIT NO. S.P.		E-6055	
ISSUED BY		MICROFILM RECORD	
ISSUANCE DATE		1-23-64	
VALUATION		\$ 13,600	
R.U.F. FEE		\$	
S.M.I. FEE		\$	
PLAN CK. FEE		\$	
SEWER INCL. FEE		\$	
PERMIT FEE		\$ 49.00	
TOTAL FEES		\$	
REMARKS AND/OR VARIANCES			
PLANS AND APPLICATION REEL NO. 136 FRAME NO. 102 TO INSPECTION RECORD REEL NO. 128 FRAME NO. 613 TO JOB FILE REEL NO. TO P 8927497 - final			