

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>H-9631</i>	LOCATION <i>4507 - U St.</i>			
DATE <i>12/28/37</i>	PURPOSE <i>Erect new dwlg. - gar.</i>			
ZONE <i>2 - 7am</i>	OWNER <i>Concil Hoffman</i>			
	ARCH'T. <i>H. R. Meckley</i>			
	CONTR. <i>H. R. Meckley</i>			
VAL. <i>2800⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>3</i>	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS			BOILER ROOMS	<i>2580'</i>
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
12/31/37	1 ST /NSP. Form replaced ^{OK} AW Campbell
12/31/37	2 ND /NSP. Form ^{OK} AW Campbell
1-28-38	3 " Lock - ^{OK} AW Campbell
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>