

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>H-4322</i>	LOCATION <i>2417 - Portola Way</i>
DATE <i>5/18/36</i>	PURPOSE <i>Erect new rear porch of</i>
ZONE	OWNER <i>L. V. Islip</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>22500</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
5/20/34	1st Insp Forms OK R.H.D.
COMPLETE AND O. K.	INSPECTOR