

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.	JOB ADDRESS		3448 JOLA CIRCLE	
FINAL INSPECTIONS	INSPECTION AREA	5		
LEGAL DESCRIPTION				
LOT 165 SOUTHWATE #1				
TITLE AND NAME				
GEN. CONTR. ROBIN CO.				
ELEC. CONTR.				
PLBG. CONTR.				
MECH. CONTR.				
ARCH. ENGR.				
OWNER HARBOUR HOME & GARDEN				
541 S. TYLER ST., EL MONTE, CALIF.				
CERTIFICATE OF OCCUPANCY				
ISSUED BY	DATE	CONST. LOAN LENDER		
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.
			1	ROOMS 6
REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES
		2B-1		TREES RMVD.
SIDE YARDS	EXISTING BLDG'S SAME LOT	460 GAR.	HOW USED	
NATURE OF WORK: CONST. DWLG. & GAR. PLAN #1365				

PERMIT NO. S.P.	D-4289
ISSUED BY	
ISSUANCE DATE	12/16/59
VALUATION	\$ 13,100.
R.D.F. FEE	\$
S.M.I. FEE	\$
PLAN CK. FEE	\$
SEWER INCL. FEE	\$
PERMIT FEE	\$ 38.50
TOTAL FEES	\$

PLANS AND APPLICATION	REEL NO. 64	FRAME NO. 174	TO	175
INSPECTION RECORD	REEL NO. 64	FRAME NO. 132	TO	148
JOB FILE	REEL NO.	FRAME NO.	TO	

REMARKS AND/OR VARIANCES

Handwritten: R 510 P 034 - Plan