

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>A-1821</i>	LOCATION <i>1055 Santa Ursula Way</i>			
DATE <i>7/10/34</i>	PURPOSE <i>To add kitchen to</i>	PHONES <i>of the</i>		
ZONE <i>Mult. Fam</i>	OWNER <i>Wm L. Lewis</i>			
	ARCH'T <i>Quincy</i>			
	CONT'R <i>Quincy</i>			
VAL. <i>100.00</i>	STORIES	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK-REMARKS
7/10/34	Made Pullman in Sub A outside Kitchen & Repair to rear of Body. H.W. Campbell
	<p data-bbox="371 847 520 891">COMPLETE AND O. K.</p> <p data-bbox="1159 871 1315 891">INSPECTOR</p>